



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
September 7, 2007

Supervisor DRH

Mine Name: Flower Patch Quarry
Operator Name: Bown Stone Products, Inc.

Permit number: S/039/019
Inspection Date: August 29, 2007
Time: Noon

Inspector(s): Lynn Kunzler, DOGM

Other Participants: none

Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

Routine inspection while in the area.

Inspection Summary:

Even though there was no one on site at the time of this inspection, there has been recent disturbance, and mining equipment was observed. This site is considered 'active'. Permit fees have been paid for the current year and the Division holds a reclamation surety. There has been some expansion to the west since the last inspection, however the site is still within the permitted boundary. The operator as done a good job in keeping trash and debris picked up and disposed of. There were no erosion problems noted, even though there has been recent heavy rains in the area.

Photos were taken to document site conditions.

Conclusions and Recommendations:

This site appears to be in compliance at this time. It is recommended to continue to monitor this site when in the area.

Inspector's Signature [Signature]

LK:pb

O:\M039-Sanpete\S0390019-FlowerPatchQuarry\Inspections\Insp-08292007.doc